## **Under Review Notification**

Raised By: Steven Drouin Product #: D412-698

Date: 18.12.05 Product Name: DOOR MODIFICATIONN

		"Y" or "N" Required for Each Part Do not leave blank							Number	
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Nu	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
D412-698-035	IIN-D412-698 Rev.G	Ν	Ν	Ν	Ν	N	Υ	Υ	18-854	CHG # 002
D3779-041	D3779 Rev. C	Ν	Ν	Ν	Ν	Ν	Υ	Υ	18-854	Revise Drawing

Description of Issue:

D3779-041 needs to be updated , to incorporate a bend in the D3779-1 plate Ok to ship With Engineeing Sign off

Distribution:

VP Operations

Director of Operations
Director Quality Assurance

QC Coordinator

Director of Engineering Chief Engineer

Engineering Project Managers
Engineering Clerk

Customer Support Manager Production Engineers

Production Engineers
Production Planners
Purchasing Manager

Technical Support

Product Manager - Solutions Provider Supply Chain Director / Senior Buyer

Marketing Eugene